


Bridger Range, Ramp
 Bridger Range
 MT
 Elevation: 8000 ft
 Aspect: NE
 Specifics: Ski tracks on slope; We skied slope

Spencer Jonas
 Sat Nov 11 14:45 2017
 Co-ord: 45.82853N, -110.93153W
 Slope Angle:
 Wind Loading:

Stability:
 Air Temperature:
 Sky Cover: BKN
 Precipitation: NO
 Wind: E Light Breeze

HS105
 Stability Test Notes

Layer No
 1-19: Prob



Notes: There was an air pocket between the ice crust that formed the bottom layer and the ground. The column failed when the ice broke little ground that it was attached to, a small root and rock at the back of the column. Our layer of concern was the old September snow with no sign of instability at its interface. It is hard to interpret the ectp as a sign of instability, it seemed to be more an issue of ground movement specifically beneath the column and not an indicator of overall instability at the ground.

Advisory Region
 Bridger Range
 Bridger Range, 2017-11-13