

From e-mail 11/4/21: "Hiking up in the Bridger Range from Sacagawea Pass and noticed no faceting of the current snowpack. The snow near the pass and on the ridge is very wind affected as is to be expected and dropping into the bowl on the east side of the Pass the snowpack there has a distinct sun crust. Dug around a little bit at 8600 ft on a NE aspect and found a sun crust of about two inches with what felt like rounded grains below that. Even in the direct sun, the crust was taking a long time to rewarm and was pretty slippery..." Photo: H. Darby

Advisory Region

Bridger Range
Longitude
-110.97W
Latitude
45.90N

Forecast link: GNFAC Avalanche Forecast for Sun Nov 7, 2021
Bridger Range, 2021-11-06