

From obs. 1/29/22: "Avalanche appeared to have been caused by a breaking cornice on lookers left. Probably from Friday [1/28]." Photo: A. Pfaffinger (zoomed in from original photo)

Advisory Region
Northern Madison
Longitude
-111.33W
Latitude

45.33N
Avalanche Details: Natural cornice triggered slide SW gully of Wilson Peak
Forecast link: GNFAC Avalanche Forecast for Sun Jan 30, 2022GNFAC Avalanche Forecast for Mon Jan 31, 2022GNFAC Avalanche Forecast for Tue Feb 1, 2022GNFAC Avalanche Forecast for Wed Feb 2, 2022GNFAC Avalanche Forecast for Thu Feb 3, 2022
Northern Madison, 2022-01-30