east Mt. Henderson
Beartooths
MT
Elevation: 9450 ft
Aspect: 95°
Specifics: Collapsing, localized; We skied slope

Beau Fredlund
11/12/2022 - 11:00am
Co-ord:
Slope Angle: 29°
Wind Loading:

Stability:
Air Temperature:
Sky Cover: CLR
Precipitation: NO
Wind: Calm

HS:90

Layer Notes:
27-0cm: Problematic layer



Notes: Snowpit location was in a relatively wind sheltered area. Above the snowpit location, much of the east facing terrain was significantly wind affected/ 1F s
recent storm and not optimal for skiing. It seemed like all other aspects around the Mt. Henderson area (S, W and N) had less surface wind affect.

No avalanche activity observed.

Advisory Region
Cooke City
Longitude
-109.95W
Latitude
45.05N
Avalanche Details: Large collapses near Cooke City
Cooke City, 2022-11-13