

A snowmobiler saw this natural avalanche hit the Daisy Pass road within 10 minutes of riding by. He did a beacon search on the debris to confirm no one had been caught. It occurred about noon. This path is not very visible from the bottom and is not one that runs regularly. It killed a rider who was on the road in February 2012. The accident report has good photos of the path from afar.

Wind-loading in the start zone was the likely trigger since skiers and sledders do not access it.

A big thanks to Dan Wykoff and Ben Zavora for providing the story and pictures.

Photo: B. Zavora

Advisory Region
Cooke City
Longitude
-109.96W
Latitude
45.05N
Avalanche Details: Natural avalanche hit Daisy Pass road
Forecast link: GNFAC Avalanche Forecast for Sun Feb 26, 2023
Cooke City, 2023-02-25